


SOUTH DAKOTA
2011-2015
TRANSPORTATION IMPROVEMENT PROGRAM
(TENTATIVE)



Projects in the Mitchell Region
Sioux Falls July 21, 2010
Mitchell July 22, 2010

Prepared by:
SOUTH DAKOTA DEPARTMENT OF TRANSPORTATION
DIVISION OF PLANNING & ENGINEERING
OFFICE OF PROJECT DEVELOPMENT
700 BROADWAY AVENUE
PIERRE, SOUTH DAKOTA 57501

South Dakota Transportation Improvement Program

Public Meeting Report
Report Date 6/24/2010

Mitchell

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|---|----------------------------------------------------------------------------------------------------|----------------------------------------------|------------------------------------------------------------------------------------------------|--------|-----------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|-------------|--------------------|
| 1 | IM 0907(69)297 | 6662 | Aurora | 11.4 | I90E | I90E - EBL Fm White Lake to Approx 1 mi E of Plankinton | Remove & Replace PCCP | 2011 | 12.531 |
| 2 | IM 0905(93)251 | 01LZ | Aurora Brule Davison Hanson Lyman McCook | 0.0 | | I90 - Mitchell Area | Replace Interstate Fence | 2011 | 0.162 |
| 3 | P 0021(92) | 02H1 | Aurora Brule Buffalo Charles Mix Gregory Hanson Jerauld Mccook Sanborn | 128.6 | SD1806 SD25 SD34 SD38 SD45 US18 US281 US81 | Various highways in the Mitchell Area | Chip Seal | 2011 | 2.627 |
| 4 | P 0023(29) | 02H2 | Bon Homme Clay Union Yankton | 49.3 | I29N I29S SD19 SD37 SD46 | Various highways in the Yankton Area | Chip Seal | 2011 | 1.004 |
| 5 | P 0022(36) | 02H0 | Brookings Lincoln Minnehaha Moody Turner | 37.2 | I90E I90W SD115 SD13 SD19 US18 | Various highways in the Sioux Falls Area | Chip Seal (Shoulders only on the Interstate portions of the project) | 2011 | 0.794 |
| 6 | NH 0037(113)51 P 0045(44)27 NH 0046(50)288 P 0050(94)231 P 090L(05)263 P 0281(92)50 | 027V 028B 028A 027Z 028E 028D | Brule Charles Mix Douglas Hutchinson | 4.0 | I90EL I90L I90WL SD37 SD45 SD46 SD50 US281 | SD37 - Fm south of the Jct. with SD44 to Glynn Drive in Parkston; SD45 from the Jct. with SD44 to North St. in Platte; SD46 from Lake St. to Front St. in Wagner; SD50 from the Jct. with I90 L to Paul Gust Road in Chamberlain & from the North City Limits of Wagner to the Jct. with SD46 in Wagner.; I90 L, I90 EL & I90 WL from the east end of the Chamberlain bridge to the Jct. with SD50; US281 from the South City Limits of Corsica to East Second St. in Corsica | Joint and Spall Repair and Joint Sealing | 2011 | 0.862 |
| 7 | PH 8008(01) | 02AF | Brule | 0.0 | | Various County, City, & Township Roads in Brule County and various Township Roads in Charles Mix County | Signing & Delineation | 2011 | 0.300 |
| 8 | P 6548(03) | 02D4 | Brule | 10.5 | | Fm 350 Ave, 2 S of Pukwana, E 10.5 mi. on 251 St. to SD45 at Kimball | Chip Seal | 2011 | 0.347 |
| 9 | BRF 0044(78)291 | 5450 | Charles Mix | 0.0 | SD44 | SD44 - Platte-Winner Bridge over Missouri River | Zone Paint & Fatigue Retrofit | 2011 | 2.040 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|--------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|--------------------------------------|-----------------------------------------------------------------------|--------|--------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 10 | BRF 0018(163)360 BRF 0042(40)334 BRF 0044(152)355 BRF 0081()54 BRF 0011()82 | 029Z 02A0 02A1 02RF 02RG | Charles Mix Douglas Hutchinson McCook Minnehaha Turner | 0.0 | SD11 SD42 SD44 US18 US81 | US18 - 0.1 W of the Charles Mix Co Line Over a Creek & 0.1 E of the Charles Mix Co Line Over a Branch of the Choteau Creek; SD42 - 1.7 E of US81 Over the W Fork of the Vermillion River; SD44 - 9.1 E of SD37 Over Dry Creek, 6.5 E of SD37 Over the North Branch of Dry Creek & 1.3 W of SD19 Over the Vermillion River; US81, 3.2 Mi S of I90 Over the W Fork of the Vermillion River ; SD11, 1.2 Mi N of I90 Over Split Rock Creek | Scour Protection; | 2011 | 0.751 |
| 11 | P 0021(93) | 02H3 | Charles Mix Douglas Hutchinson Union | 52.1 | SD1804 SD44 SD48 US18 | Various highways in the Mitchell Region | Rout and Seal | 2011 | 0.188 |
| 12 | P 090L(01)332 NH 0037(102)72 EM-PH 2090(21)332 | 01BC 01BA 010Q | Davison | 5.2 | I90EL I90L I90WL SD37 SD37N SD37S | I90L - Burr St. from I90 to Havens Ave. in Mitchell; I90L - Burr St. from Spruce St. to I90; SD37 - From the North City Limits of Mitchell to the North Urban Boundary of Mitchell, Service Roads & Fm I90 South 0.2 Mi; I-90 Loop (Havens St.) from Burr St. to Ohlman Street in Mitchell | Joint Repair, Crack Sealing, Spall Repair & PCCP Panel Replacement; Reconstruction. Joint & Spall Repr, Panel Repl., Reconstruct Havens/Rowley Intersection, AC Resurfacing, ADA, Signals & Lighting | 2011 | 4.686 |
| SAFETEA-LU earmark of \$3,000,000 for SD Reconstruct I-90 loop in Mitchell (Burr to Sanborn) | | | | | | | | | |
| 13 | P 3693(01) | 01D9 | Davison | 0.4 | | Lawler St. from 1st Ave. to 5th Ave. in Mitchell | Storm Sewer, Base Course, AC Surfacing, Curb & Gutter, Municipal Water & Sewer | 2011 | 0.650 |
| 14 | P 3658(03) | 02FF | Davison | 1.1 | | W 23rd Ave, from N Ohlman St to N Main St in Mitchell | Asphalt Concrete Overlay, Storm Sewer Repair, Signing, Pavement Marking | 2011 | 0.200 |
| 15 | BRF 3630(02) | 00YW | Davison | 0.2 | | Structure on NW Edge of Lake Mitchell over Lake Mitchell | Structure & Approach Grading | 2011 | 0.584 |
| 16 | P 0ENH(204) | 02U7 | Davison | 0.0 | | Bike Path in Mitchell | Bike Path PE & Construction | 2011 | 0.537 |
| 17 | P 0047(93)0 | 026J | Gregory | 12.5 | SD47 | SD47- From the Nebraska State Line to the Jct. with US18 & Str 2.8 N of Nebraska State Line | Mill & AC Resurfacing; Deck Overlay, Approach Guard Rail & Replace Bridge Rail | 2011 | 2.862 |
| 18 | BRF 0025(64)75 BRF 0042(39)313 | 029U 029X | Hanson Miner | 0.0 | SD25 SD42 | SD25 - 7.5 S of SD34 Over Bloom Creek; SD42 - 9.5 & 10.4 E of the Davision Co Line Over Bloom Creek | Scour Protection | 2011 | 0.271 |
| 19 | P 0262(06)356 | 02QD | Hanson | 17.5 | SD262 | SD 262 from the Jct. with I 90 to the Jct. with SD 42 | Mill & AC Resurfacing & Draining Improvements | 2011 | 3.542 |
| 20 | BRO 8034(24) | 00JS | Hutchinson | 0.4 | | Strs on Walnut St & on Maple St in Parkston Over Pony Creek (City owned) | Structures & Approach Grading | 2011 | 0.485 |
| 21 | P 6236(02) | 6649 | Jerauld | 4.0 | | Fm US281 E 4 mi. on 221 St to 392 Ave at Alpena | Grading Base Course, Milling, & AC Surfacing | 2011 | 1.500 |
| Total Project = \$1.5 mill. (Available STP and Match = \$0.542; Local Funds and Grant = \$0.958 mill.) | | | | | | | | | |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|--------------------------------------------------------------------------------------------------------|-----------------------------------|--------------|-------------------------------|--------|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-------------|--------------------|
| 22 | PS 6329(03) | 02HU | Lake | 0.0 | | Highland Ave. in Madison; Farmers Elevator, DOT#381204L | Railroad Crossing Rehabilitation | 2011 | 0.086 |
| 23 | P 6327(08) | 02DA | Lake | 7.0 | | Fm SD34/US81 2W of Junius, N 7 mi. on 446 Ave. (Co. Rd R51) | Asphalt Concrete Overlay | 2011 | 1.100 |
| Total Project = \$1.1 mill. (Available STP & State Match = \$0.547 mill.; Local Funds = \$0.553 mill.) | | | | | | | | | |
| 24 | BRO 8040(09) | 4636 | Lake | 0.4 | | 5.4 E & 1.0 S, & 5.2 E & 1.0 S of Nunda Over Battle Creek | Structures & Approach Grading | 2011 | 0.300 |
| 25 | IM 0292(14)64 | 00X0 | Lincoln | 0.0 | I29N | I29 - NBL, Over I29, SD44 Interchange | Deck Overlay, Approach Slabs, Approach Guardrail & Approach Pavement | 2011 | 0.275 |
| 26 | IM 0291(107)59 IM 0901(147)379 | 01C5 01C6 | Lincoln Minnehaha | 0.0 | I29N I90E | I29 & I90 - Sioux Falls Area | Replace Interstate Fence | 2011 | 0.137 |
| | | | Moody | | | | | | |
| 27 | IM 0291(112)0 | 01M4 | Lincoln Union | 0.0 | | I29 - Yankton Area | Replace Interstate Fence | 2011 | 0.073 |
| 28 | IM 2292(89)0 BRF 2292(91)2 | 01SH 029F | Lincoln Minnehaha | 0.0 | I229N I229NF I229S | I229 - Louise Ave Over I229, I229 SBL & NBL over the Big Sioux River, Western Ave Over the Big Sioux River, I229 NBL & SBL Over Minnesota Ave, I229 NBL & SBL Over Cliff Ave, 26th Street Over I229 and 10th Street Over I229; Western Ave over I229 | Epoxy Chip Seals & Joint Modification | 2011 | 1.587 |
| 29 | P 0011(55)63 P 0044(147)397 | 01SD 01SE | Lincoln Turner | 0.0 | SD11 SD44 | SD11 - 6 mi S Minnehaha Co Line over Nine Mile Ck; SD44 - 0.9 W Jct SD 17 over Long Ck: 1.4 E Jct SD 19 over Vermillion River | Epoxy Chip Seal | 2011 | 0.217 |
| 30 | P 1344(01) | 02J0 | Lincoln | 0.0 | | S Solberg Ave. from W 59th St, S to W 69th St N in Sioux Falls | PE, ROW Acquisition, Grading, Base Course, Asphalt Concrete, Curb & Gutter, Storm Sewer | 2011 | 3.500 |
| 31 | PP 000S() | 02MF | Lincoln Minnehaha Union | 0.0 | | D&I Railroad from Elk Point to Canton, Big Sioux River to Beresford, and Sioux Falls to Dell Rapids. E&E Railroad from Brandon to Ellis. | Replace Railroad Crossing Crossbuck Signs | 2011 | 0.050 |
| 32 | IM 2292(88)0 | 01QT | Lincoln | 0.0 | I229N I229S | Solberg/Tallgrass Overpass | Structure | 2011 | 3.060 |
| 33 | P SRTS(17) | 02UD | Lincoln | 0.0 | | Tea | Safe Routes to School (SRTS) Project | 2011 | 0.065 |
| 34 | P 6149(05) | 00Z7 | McCook | 6.0 | | Fm 254 St at Montrose, N 6 mi. on Valley Road to 248 St | Grind in place AC, AC Overlay, Slope Flattening | 2011 | 0.960 |
| 35 | IM 0908(91)364 | 02KJ | McCook | 0.0 | I90E | US81 over I90; US81/I90 Interchange; Structure #44-110-125 | Bridge Repair Due To Over-Height Impact Damage | 2011 | 0.050 |
| 36 | P 0034(137)350 | 024V | Miner | 7.0 | SD34 | SD34 - Fm west of the Sanborn/Miner County Line to Roswell & Str. 2.1 & 5.2 E of Sanborn Co Line over Crk | Mainline - Mill & AC Resurfacing & Str. - Membrane & AC Overlay | 2011 | 1.729 |
| 37 | P-PH 0038(27)348 | H034 | Minnehaha | 14.7 | SD38 | From the Jct with SD19 to the beginning of the divided highway at Sioux Falls | Mill & AC Resurfacing, ADA, Add turn lanes | 2011 | 4.659 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|----|-------------------------------------------------|----------------------|------------|--------|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-------------|--------------------|
| 38 | PP 1261(11) | 02HW | Minnehaha | 0.0 | | Cliff Ave. by 20th St. in Sioux Falls; BNSF, DOT #075474T | Railroad Signals | 2011 | 0.250 |
| 39 | PP 0011(67)81 | 02HY | Minnehaha | 0.0 | SD11 | SD11 in Corson; BNSF 097857G | Upgrade railroad signal system & rehabilitate crossing | 2011 | 0.325 |
| 40 | P 1138(01) | 00KF | Minnehaha | 0.9 | | West Ave, fm Russell to 6th in Sioux Falls | PCCP Surfacing | 2011 | 4.119 |
| 41 | PH 2042(02) | 01X8 | Minnehaha | 0.0 | | Intersection of 10th & Cliff Ave in Sioux Falls | Add Additional Left-Turn Lanes on All Legs of Intersection | 2011 | 1.000 |
| 42 | EM 1225(03) | 00UH | Minnehaha | 0.0 | | Fm Downtown in Sioux Falls to E of Sioux Falls | Railroad Relocation Plan | 2011 | 34.661 |
| 43 | IM 0909()399 | 02P2 | Minnehaha | 1.3 | I90E I90W | I90 EBL & WBL - Fm E of Cliff Ave to Slip Up Creek E of I229 | I90 - PCCP Resurfacing | 2011 | 5.070 |
| 44 | P SRTS(15) | 02UB | Minnehaha | 0.0 | | Sioux Falls | Safe Routes to School (SRTS) Project | 2011 | 0.043 |
| 45 | P SRTS(16) | 02UC | Minnehaha | 0.0 | | St. Mary, Sioux Falls | Safe Routes to School (SRTS) Project | 2011 | 0.038 |
| 46 | P 0034(130)406 | 6679 | Moody | 16.2 | SD34 | SD34 - Fm 0.2 Mi W of I29 to the Minnesota State Line | AC Surfacing | 2011 | 8.589 |
| 47 | P 0013(13)105 P 0032(05)421 | 01SV 01TK | Moody | 11.4 | SD13 SD32 | SD13 - Fm the Jct. With SD34 to S of the Moody/Brookings Co Line. SD32 - Fm the W City Limits to the Jct. With SD13 in Flandreau | Mill & AC Resurfacing & ADA Upgrades | 2011 | 3.785 |
| 48 | P 6215(03) | 02J6 | Sanborn | 13.0 | | From SD34 1.5 mi. W of Artesian, N 13 mi. on 413 Ave. (Co. Rd 24-0) to 220 St (County Line) | Chip Seal | 2011 | 0.429 |
| 49 | BRO 8056(09) | 00Z1 | Sanborn | 0.2 | | Structure 2W & 6.3N of Woonsocket over Sand Creek | Structure & Approach Grading | 2011 | 0.250 |
| 50 | P SRTS(12) | 02U8 | Turner | 0.0 | | Centerville | Safe Routes to School (SRTS) Project | 2011 | 0.203 |
| 51 | NH 0081(84)6 P 0153(02)1 PH-P 0052(02)342 | 01BX 01TA 6700 | Yankton | 8.8 | SD153 SD52 US81 | US81 - AC Segment between Yankton and SD46, SD52 - Fm Chalkstone Road (West City Limits) to Summit in Yankton Including the Intersection of SD52 & Summit St, SD153 - From the Jct of SD52 to SD50 | Mill & AC Resurfacing; Traffic Signals, Intersection Modification & ADA Upgrades | 2011 | 3.625 |
| 52 | P 4701(14) P 4718(03) P 4727(03) | 01KZ 01TT 01TU | Yankton | 1.1 | | Douglas Ave from 23rd St to 25th St ; 15th St from Burleigh St to Whiting Dr in Yankton; Summit St from 9th St to 15th St in Yankton | Grading, Pavement, C&G, Storm Sewer, Sidewalk | 2011 | 2.101 |
| 53 | P 6366(04) | 01PU | Yankton | 0.1 | | 1.1S & 2.4W of Mission Hills on 309 St. near the James River SN 68-156-182 | Roadway Stability Repair | 2011 | 0.300 |
| 54 | BRO 8068(07) | 6596 | Yankton | 0.2 | | 2.8 E & 1.8 N of Utica Over the Beaver Creek Spillway | Structure & Approach Grading | 2011 | 0.837 |
| 55 | PH 000S(184) | 012X | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Durable Pavement Marking | 2011 | 0.525 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|----|----------------|------|------------|--------|-------|---------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 56 | PH 000S(219) | 02C4 | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Install Rumble Strips | 2011 | 0.300 |
| 57 | P 000S(00)312 | 00ZM | Regionwide | 0.0 | | Various Locations in the Mitchell Region | County Pavement Marking | 2011 | 0.372 |
| 58 | IM 000S(264) | 02NW | Regionwide | 0.0 | | Mitchell Region | Snow Gates & Sign Installation | 2011 | 1.361 |
| 59 | BRF 000S(202) | 01XH | Statewide | 0.0 | | Statewide | Bridge Inspection and Equipment | 2011 | 2.550 |
| 60 | P 000S(194) | 01MR | Statewide | 0.0 | | Statewide | Safe Routes to School | 2011 | 0.100 |
| 61 | PH 0000(25) | 00LJ | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement; | 2011 | 0.065 |
| 62 | PH 0000(47) | 02AH | Statewide | 0.0 | | Public Roads Traveled Statewide | Preliminary Engineering for Conducting Road Safety Audit Reviews (RSAR) | 2011 | 0.030 |
| 63 | HS 2701(13)11 | 02CV | Statewide | 0.0 | | Statewide | Local Government Traffic Engineering Services Performed by the SDDOT Traffic & Safety Engineer | 2011 | 0.115 |
| 64 | BR NBIS(26) | 00ZQ | Statewide | 0.0 | | Statewide | Bridge Inspections, Scour Analysis | 2011 | 0.636 |
| 65 | PP 000S() | 02ME | Statewide | 0.0 | | DM&E Fm MN Stateline to Rapid City, Onida to Blunt, Redfield to Mansfield, & Huron to Yale. | Replace Railroad Crossing Crossbuck Signs | 2011 | 0.220 |
| 66 | PS 000S() | 02MG | Statewide | 0.0 | | Statewide | Federal match up to \$7,500 per site for closure of highway-rail grade crossing when railroad provides matching railroad funds to the Community | 2011 | 0.015 |
| 67 | PS 000S() | 02MH | Statewide | 0.0 | | Statewide | Inventory Compliation & Analysis | 2011 | 0.045 |
| 68 | PS 000S() | 02MJ | Statewide | 0.0 | | Statewide | Preliminary Engineering for Railroad Safety Projects | 2011 | 0.060 |
| 69 | PH 000S() | 02N7 | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2011 | 0.065 |
| 70 | IM 000S() | 02NU | Statewide | 0.0 | | Statewide | Guardrail Replacement | 2011 | 2.000 |
| 71 | P 000S() | 02TS | Statewide | 0.0 | | Statewide | Wetland Mitigation | 2011 | 0.500 |
| 72 | P DBEC()11 | 02TU | Statewide | 0.0 | | DBEC Certification Services Statewide for CY2011 | DBEC Certification Services Statewide for CY2011 | 2011 | 0.066 |
| 73 | SS FY10() | 02TT | Statewide | 0.0 | | DBE Supportive Services for CY11 | DBE Supportive Services for CY11 | 2011 | 0.156 |
| 74 | HR Z() | 02TQ | Statewide | 0.0 | | Statewide | Operations of Existing ITS Services and Facilities, Including the 511 and SafeTravel USA Traveler Information Services, and Annual Operations and Support of Fixed and Portable Dynamic Message Signs, Environmental Sensor Stations, and Mobile Data Collection for Winter Maintenance Decision Support. | 2011 | 1.100 |
| 75 | BRF 6169(05) | 01DS | Aurora | 0.2 | | Structure 8N of White Lake over a creek | Structure & Approach Grading | 2012 | 0.400 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|----|-------------------------------------------------|----------------------|---------------------------------------------------------|--------|---------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 76 | IM 0905()251 | 02P8 | Aurora Brule Davison Hanson Lyman McCook | 0.0 | | I90 in the Mitchell Area | Replace Interstate Fence | 2012 | 0.260 |
| 77 | P-BRF 0025(58)07 | 01D3 | Bon Homme Hutchinson | 18.6 | SD25 | SD25 - Fm the Jct. with SD50 to the Jct. with US18 excluding the town of Scotland & Structures Over Lone Tree Creek, 0.7 Mi S of the Junction of US18 & 2.7 S of the Hutchinson Co Line Over a Creek | Mill & AC Resurfacing; Replace Structures (RCBC) & Approach Grading | 2012 | 5.046 |
| 78 | NH 0050(87)353 P 0037()9 | 00L9 02RJ | Bon Homme | 0.0 | SD37 SD50 | SD50 - 1.0 W of SD37S Over Emanuel Creek; SD37 - 2.8 W & 0.2N of Springfield Over Emanuel Creek | Bent Cap & Column Repair; Deck Overlay & Approach Pavement | 2012 | 0.172 |
| 79 | BRF 6208(04) | 02EE | Bon Homme | 0.2 | | Structure 0.5N & 3.3W of Scotland over Dawson Creek | Structure & Approach Grading | 2012 | 0.262 |
| 80 | IM 0905(96)258 | 01QR | Brule Lyman | 7.4 | I90E I90W | I90 - Fm Oacoma Thru The Missouri River Structure | Mill & PCCP Resurfacing, Deck Overlay, Replace Joints, Bridge Rail Rep, Appr Slabs, Zone Paint & Guard Rail | 2012 | 10.632 |
| 81 | P 0050(93)222 | 025A | Brule | 8.7 | SD50 | SD50 - Fm the Buffalo/Brule County Line to K Avenue in Chamberlain | Mill & AC Resurfacing, Pipe | 2012 | 3.184 |
| 82 | P 6506(04) P 6804(06) | 02DJ 02DK | Brule | 13.5 | | Fm 350 Ave, 4N of Pukwana, W 6 mi. on 245 St (FAS 6506) to SD50; Fm I 90 Exit 265, S 7.5 mi. on 344 Ave (FAS 6804) to 257 St. | Chip Seal | 2012 | 0.456 |
| 83 | P 0050()241 | 02QJ | Brule Charles Mix | 26.8 | SD50 | SD50 from the east Jct. with I90 to north of the west Jct with SD44 | Mill & AC Resurfacing | 2012 | 6.413 |
| 84 | P 6198(03) | 00ZK | Charles Mix | 10.0 | | From 7N of Lake Andes at 382 Ave, E 10 mi. on 285 St to US281 (Co. Rd H0-34, Seg. 54) | Asphalt Overlay | 2012 | 1.600 |
| 85 | P 0044(151)305 P 0045(41)27 NH 0281(91)40 | 02BF 02BG 02BE | Charles Mix Douglas | 2.3 | SD44 SD45 US281 | SD44/SD45 - Through Platte; US281 - Through Armour | Curb Ramp Upgrades | 2012 | 0.425 |
| 86 | NH-P 0050(91)396 | 0237 | Clay | 13.1 | SD50E SD50EL SD50L SD50W SD50WL | SD50- WBL, Fm Yankton/Clay County Line to Vermillion; SD 50 E from east of Meckling to the Jct. with SD50 L And SD50 L, SD50 EL and SD50 WL from the Jct. with SD50 to the begin of the concrete in Vermillion | Grading and PCCP Surfacing; Mill & AC Overlay | 2012 | 13.157 |
| 87 | BRF 0050(86)407 BRF 0019()5 | 00KR 02RM | Clay | 0.0 | SD19 SD50 SD50E | SD50 - 2.0 NW, 1.0 NW & the East Edge of Vermillion Over SD50L/Railroad, the Vermillion River, & SD 50L; SD19, Str #14-107-194 1.2 N of SD50 Over the Vermillion River | Deck Overlay/Epoxy Chip Seal, Rail & Approach Slab; Epoxy Chip Seal on 14-107-194. | 2012 | 1.543 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|--------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------|---------------------------|--------|---------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 88 | P 0011(58)27 P 0046(46)356 P 0018(161)367 | 01R1 01R2 01R0 | Clay Lincoln Union | 0.0 | SD11 SD46 US18 | US18 - 0.7 W of Canton Over Beaver Creek; SD11 - 12.4 S Jct SD46 over West Union Crk; SD46 - 0.2 E of Jct SD19 S over Vermillion River | US18 -Deck Overlay, Approach Guardrail, & Approach Slabs; SD11 - Deck Overlay, Approach Slabs and Approach Guardrail; SD46 - Deck Overlay, Replace Bridge Rail, Approach Slabs & Approach Guardrail | 2012 | 0.668 |
| 89 | P 5741(03) | 4535 | Clay | 0.3 | | Stanford St fm Main St. to Cherry St. (SD50L) Vermillion | Grading, Storm Sewer, C&G, PCCP Paving, Lighting, Bike Path | 2012 | 1.500 |
| Total = \$1.5 (STP w/Match = \$0.748; Local Funds = \$0.752) | | | | | | | | | |
| 90 | PH 8014(32) | 02AP | Clay | 0.0 | | Various County, City, and Township Roads in Clay County | Signing & Delineation | 2012 | 0.300 |
| 91 | BRO 8014(30) | 00K5 | Clay | 0.2 | | 7 S & 14.1 E of Irene Over Baptist Creek | Structure & Approach Grading | 2012 | 0.283 |
| 92 | P 019A(27)27 NH 0018(164)425 P 0019(34)37 P 0044(153)392 P 0046(51)346 | 02BD 02BA 02BB 02BC 02G3 | Clay Turner Yankton | 1.5 | SD19 SD19A SD44 SD46 US18 | SD19A - Through Centerville; SD19 - Through Viborg; US18 - Through Davis; SD44 - Through Parker & Chancellor; SD 46 through Irene | Curb Ramp Upgrades | 2012 | 0.224 |
| 93 | P 3698(02) | 02FG | Davison | 0.3 | | E 5th Ave, from N Main St to N Burr St in Mitchell | Asphalt Concrete, Base Course, Storm Sewer, Curb & Gutter, Sidewalk, Signing | 2012 | 0.450 |
| 94 | P 6042(02) | 01P0 | Davison | 1.0 | | From 12W of Ethan, W 1 mi. on 265 St between 398 Ave & 399 Ave | Grading & Slope Flattening | 2012 | 0.500 |
| 95 | P 6138() | 02SK | Douglas | 3.0 | | From 396 Ave., 7E & 3N of Corsica, E 3 miles on 270 St. (Co. Rd 580-5) to 399 Ave. | Asphalt Concrete Overlay | 2012 | 0.480 |
| 96 | P 0047(91)2 P 0044(157)279 P 1806()23 | 01R3 01R4 02RL | Gregory | 0.0 | SD1806 SD44 SD47 | SD47 - 2.2 S of Jct SD44 over a Crk; SD44 - 5.3 E of Jct SD47 over a Creek; SD1806 - 8.0 N of Jct US 18 over Whetstone Ck | SD47 & SD44 Strs - Deck Overlay, Approach Guard Rail, Approach Slabs & Replace Bridge Rail; SD1806 Str - Deck Overlay, Approach Guardrail, Approach Pavement | 2012 | 0.562 |
| 97 | PH 8027(30) | 02AQ | Gregory | 0.0 | | Various County, City, & Township Roads in Gregory County | Signing & Delineation | 2012 | 0.400 |
| 98 | BRO 8027(28) | 00JY | Gregory | 0.2 | | 3.1 W & 2 S of SD44/SD47 Over a Creek | Structure & Approach Grading | 2012 | 0.260 |
| 99 | P 6233(06) | 01W3 | Hanson | 0.5 | | From 8W & 1.25N of Emery just N of 260 St, N 0.5 mi. on 421 Ave to just before 259 St (Co. Rd #5) | Box Culvert, Grading, AC Surfacing | 2012 | 0.530 |
| 100 | P 0034(138)312 | 020A | Jerauld | 0.1 | SD34 | SD 34 - 0.1 mile east of Dakota Ave in Wessington Springs | Replace Culvert | 2012 | 0.453 |
| 101 | P 6087(01) | 01FG | Lake | 0.5 | | Center St from Washington Ave to Division Ave in Madison | Grading, Asphalt Surfacing, Storm Sewer, Sidewalk, Curb & Gutter | 2012 | 0.976 |
| 102 | BRO 8040(08) | 5771 | Lake | 0.2 | | 2 E & 2.2 N of Rutland Over Battle Creek | Structure & Approach Grading | 2012 | 0.244 |
| 103 | BRF 6320(04) | 00ZH | Lake | 0.2 | | Structure 3S & 1.2W of Lake Campbell over Battle Creek | Structure & Approach Grading | 2012 | 0.468 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|---------------------------------|--------------|-------------------------------|--------|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-------------|--------------------|
| 104 | P 0044(154)395 P 0017(07)43 | 0255 026L | Lincoln Turner | 20.0 | SD17 SD44 | SD44 - Fm the south Jct. with SD19 to the Jct. with SD17; SD17 from Lennox to the Lincoln/Minnehaha County Line | Mill & AC Resurfacing | 2012 | 5.373 |
| 105 | P 0011(49)68 | 00CP | Lincoln Minnehaha | 2.8 | SD11 SD11N SD11S | SD11 - Fm Appx 1200' S of 69th St. N to approx. 1000 ft S of 26th Street | Urban Grading & PCCP Surfacing; Shoulder Widening & AC Resurfacing | 2012 | 14.623 |
| 106 | BRF 6116(02) | 5551 | Lincoln | 0.2 | | 3 N & 4.9 W of Beresford Over a Creek | Structure & Approach Grading | 2012 | 0.275 |
| 107 | IM 0292()073 IM 0909()397 | 02P3 02P4 | Lincoln Minnehaha | 0.0 | I29N I90E | I29 NB: Tea, Madison & Benson Rd Interchanges; I90: 1.3 E of I29, 1.1 & 0.8W of SD115 Over the Big Sioux River, Silver Creek & Railroad | Approach Slab & Approach Pavement Repair/Replacement | 2012 | 1.014 |
| 108 | IM 0909()379 IM 0292()59 | 02P9 02PA | Lincoln Minnehaha Moody | 0.0 | | I90 - Sioux Falls Area; I29 - Sioux Falls Area | Replace Interstate Fence | 2012 | 0.260 |
| 109 | BRF 6344(15) | 01DU | McCook | 0.2 | | Structure 1.6E of Emery over Wolf Creek | Structure & Approach Grading | 2012 | 0.355 |
| 110 | NH 0081()81 | 02Q3 | Miner | 10.8 | US81 | US81 - Fm the West Jct. with SD34 to Madison | Mill & AC Resurfacing | 2012 | 2.828 |
| 111 | P 2115(39) EM-IM 0909(80)399 | 6668 4437 | Minnehaha | 1.7 | I90E I90W | Cliff Ave - Fm N 60th Street N to Dike Dr. & Cliff Ave Interchange | Cliff Ave - Urban Grading, PCC Surf & Roadway Lighting & I90 - Reconstruct Cliff Ave Interchange | 2012 | 18.202 |
| 112 | P 0042(38)365 | 004E | Minnehaha | 0.0 | | 12th St - 1.9 E of I29 over the Railroad in Sioux Falls | Paint Super Structure | 2012 | 0.259 |
| 113 | PS 1261(10) | 011B | Minnehaha | 0.0 | | Cliff Ave. by 14th St. in Sioux Falls, crossing 381-656W, BNSF | Crossing Surface Rehabilitation, Approach Improvement & Preliminary Engineering | 2012 | 0.240 |
| 114 | NH 2115(45)87 | 4440 | Minnehaha | 1.0 | | Cliff Ave fm Benson Rd to North 60th Street in Sioux Falls | Grading, PCCP Surfacing & Roadway Lighting, ROW | 2012 | 7.421 |
| 115 | P 1432(03) P 1361() | 02CY 02S9 | Minnehaha | 1.2 | | 57th Street, from Sycamore Ave. E 1 mi. to SD11 (FA 1432) and 41st Street from SD11 W 0.2 mi. to Harmodon Park (FA 1361) in Sioux Falls | Grading, PCCP Surfacing, ROW | 2012 | 4.800 |
| 116 | BRF 6319(03) | 00Z0 | Moody | 0.2 | | Structure 1E & 10.9N of Coleman over a creek | Structure Rehabilitation | 2012 | 0.100 |
| 117 | PH 8056(11) | 02AR | Sanborn | 0.0 | | Various County, City, & Township Roads in Sanborn County | Signing & Delineation | 2012 | 0.400 |
| 118 | P 0019(33)31 P 0018(165)419 | 0243 0242 | Turner | 12.0 | SD19 US18 | SD19 - Fm the west Jct. with SD46 to the south Jct. with US18; US18 - From the South Jct of SD19 to the North Jct. of SD19 | Mill & AC Resurfacing | 2012 | 2.733 |
| 119 | NH 0050(89)381 | 012A | Yankton | 1.0 | SD50 | SD50 - Fm the US81 N Jct W to the Yankton City Limits | Roadway Lighting | 2012 | 0.308 |
| 120 | P 6370(09) | 02DG | Yankton | 4.4 | | Fm the East County Line (452 Ave.) 1E of Volin, W 1 mi. on 306 St., NW 1.9 mi., & W 1.5 mi. on 305 St. to 448 Ave. | Asphalt Concrete Overlay, Rut Repair | 2012 | 0.450 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|-----------------------------------------------------------|----------------------|---------------------------------------------------------|--------|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|-------------|--------------------|
| 121 | P 6366(05) | 02DH | Yankton | 2.7 | | Fm the East Yankton City Limits, just E of Alumax Drive on Whiting Drive, NE 2.7 mi. to 444 Ave. | Asphalt Concrete Overlay, Rut Repair | 2012 | 0.400 |
| 122 | IM 0291()0 | 02PB | Yankton | 0.0 | | I29 - Yankton Area | Replace Interstate Fence | 2012 | 0.260 |
| 123 | PH 000S(207) | 01UF | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Durable Pavement Marking | 2012 | 0.525 |
| 124 | PH 000S(220) | 02C5 | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Install Rumble Strips | 2012 | 0.300 |
| 125 | P 000S(00)322 | 01ER | Regionwide | 0.0 | | Various Locations in the Mitchell Region | County Pavement Marking | 2012 | 0.372 |
| | State = 60%, \$0.223 Local = 40%, \$0.149 Total = \$0.372 | | | | | | | | |
| 126 | BRF 000S(203) | 01XJ | Statewide | 0.0 | | Statewide | Bridge Inspection and Equipment | 2012 | 1.561 |
| 127 | P 000S(195) | 01MS | Statewide | 0.0 | | Statewide | Safe Routes to School | 2012 | 0.100 |
| 128 | PH 0000(25) | 00LJ | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2012 | 0.065 |
| 129 | PH 0000(48) | 02AJ | Statewide | 0.0 | | Public Roads Traveled Statewide | Preliminary Engineering for Conducting Road Safety Audit Reviews (RSAR) | 2012 | 0.030 |
| 130 | HS 4701(13)12 | 02CT | Statewide | 0.0 | | Statewide | Local Government Traffic Engineering Services Performed by the SDDOT Traffic & Safety Engineer. | 2012 | 0.115 |
| 131 | BR NBIS(27) | 01EU | Statewide | 0.0 | | Statewide | Bridge Inspections, Scour Analysis | 2012 | 1.136 |
| 132 | PH 000S() | 02N8 | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2012 | 0.065 |
| 133 | IM 000S() | 02P6 | Statewide | 0.0 | | Statewide | Guardrail Replacement | 2012 | 2.000 |
| 134 | P 000S() | 02TX | Statewide | 0.0 | | Statewide | Wetland Mitigation | 2012 | 0.500 |
| 135 | P DBEC()12 | 02TV | Statewide | 0.0 | | DBEC Certification Services Statewide for CY2012 | DBEC Certification Services Statewide for CY2012 | 2012 | 0.068 |
| 136 | SS FY11() | 02TW | Statewide | 0.0 | | DBE Supportive Services for CY12 | DBE Supportive Services for CY12 | 2012 | 0.159 |
| 137 | P 0281(93)85 P 0034(144)317 P 1804(11)113 | 01S5 01S6 01S7 | Aurora Charles Mix Jerauld | 0.0 | SD1804 SD34 US281 | US281 - 1.3 S County Line over Firesteel Ck; SD34 - 1.4 W Jct US 281 over Firesteel Ck; SD1804 - 5.9 S Jct SD 44 & SD 50 over Platte Ck & 7.1 S Jct SD 44 & SD 50 over a Ck | US281 & SD34 Strs - Epoxy Chip Seal; SD1804 - Strs Deck Overlay & Replace Bridge Rail | 2013 | 0.454 |
| 138 | BRO 8002(09) | 00ZG | Aurora | 0.2 | | Structure 6.8E & 7N of Plankinton over Firesteel Creek | Structure & Approach Grading | 2013 | 0.252 |
| 139 | BRO 8002(01) | 00G7 | Aurora | 0.2 | | Str. 11.6 S & 2 W of White Lake Over Platte Creek | Structure & Approach Grading | 2013 | 0.280 |
| 140 | IM 0907()293 | 02PH | Aurora | 0.0 | I90E I90W | 3.2 Mi W of the White Lake Exit Over Platte Creek | Scour Protection | 2013 | 0.192 |
| 141 | IM 0905()251 | 02PJ | Aurora Brule Davison Hanson Lyman McCook | 0.0 | | I29 - Mitchell Area | Replace Interstate Fence | 2013 | 0.531 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|-----------------------------------------------|----------------------|----------------------|--------|--------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 142 | BRO 8012(15) | 01DL | Charles Mix | 0.2 | | Structure 8N & 7.1E of Lake Andes over Andes Creek | Structure & Approach Grading | 2013 | 0.244 |
| 143 | P 0046(47)356 | 025D | Clay Union | 8.9 | SD46 | SD46 - Fm E of the Vermillion River Str to W of the Jct. with I29.; SD46 from west of the Jct. with I29 to 13th St. SW in Beresford | Mill & AC Resurfacing (Exception MRM 356.61 to 356.670) & Extend Culvert; Pavement Grinding | 2013 | 1.883 |
| 144 | P 0019(35)4 P 0050(96)424 P 0048(08)375 | 01S8 01S9 01SA | Clay Union | 0.0 | SD19 SD48 SD50 | SD19 - 0.8 W Jct SD 19N over Vermillion River; 0.6 W Jct SD 19 N over SD RR; SD50 - 2.1 W Iowa State Line over Brule Ck; SD48 - 3.5 E Jct I 29 over Brule Ck; 2.5 W Iowa State Line over West Union Ck; 2.1 W Iowa State Line over East Union Ck; 0.9 W Iowa State Line over Drainage Ditch | Epoxy Chip Seal, Approach Slabs & Replace Joints; Column Repair 64-105-161 | 2013 | 0.666 |
| 145 | BRO 8014(31) | 00K4 | Clay | 0.2 | | 9.6 S & 2 E of Irene Over Clay Creek | Structure & Approach Grading | 2013 | 0.237 |
| 146 | BRF 6475(08) | 01WB | Clay | 0.2 | | Structure 13E & 1.1S of Irene over Ash Creek (29810 Univ. Rd) | Structure & Approach Grading | 2013 | 0.360 |
| 147 | P 3699(01) | 01DA | Davison | 1.0 | | Spruce St. from Rowley to Ohlman in Mitchell | Grading, Storm Sewer, Curb & Gutter, Base Course, AC Surfacing (Reconstruction from Rural to Urban Section) | 2013 | 1.400 |
| 148 | P 3708(02) | 02JB | Davison | 0.2 | | N. Rowley Street from W 2nd Ave. to W 5th Ave. in Mitchell | Base Course, Asphalt Concrete, Sidewalk, Curb & Gutter, Storm Sewer, Signing | 2013 | 0.261 |
| 149 | BRF 6221(14) | 01XY | Davison | 0.2 | | Structure 8W & 5.8N of Ethan over a creek | Structure & Approach Grading | 2013 | 0.250 |
| 150 | PH 8022(14) | 02AS | Douglas | 0.0 | | Various County, City, & Township Roads in Douglas County | Signing & Delineation | 2013 | 0.400 |
| 151 | BRO 8027(11) | 00JN | Gregory | 0.2 | | 4.2 E & 2.8 N of Bonesteel Over North Scalp Creek | Structure & Approach Grading | 2013 | 0.252 |
| 152 | P 0044()362 | 02QN | Hutchinson | 15.3 | SD44 | SD 44 from the James River to the Jct. with US 81 | Mill & AC Resurfacing | 2013 | 2.512 |
| 153 | P 0281(90)103 | 01QZ | Jerauld | 0.0 | US281 | US281 - 1.3 S of Beadle Co Line over Sand Crk | Deck Overlay, Approach Guard Rail, Approach Slabs & Replace Bridge Rail | 2013 | 0.223 |
| 154 | P 0019(31)73 | 025Z | Lake Minnehaha | 23.5 | SD19 | SD19 - Fm the Jct. of SD38 to the Jct of SD34 | Shoulder Widening; Grading & Interim Surfacing | 2013 | 15.071 |
| 155 | BRO 8040(15) | 00ZB | Lake | 0.2 | | Structure 1.9E & 1N of Rutland over Battle Creek | Structure & Approach Grading | 2013 | 0.252 |
| 156 | IM 0293(96)75 IM 2292(90)0 | 01QS 020Q | Lincoln Minnehaha | 5.0 | I229N I229S I29N I29S | I229/I29 - Area Improvement | Reconstruct | 2013 | 24.374 |
| 157 | BRO 8042(31) | 5552 | Lincoln | 0.2 | | 9.7 S & 3.0 E of Lennox Over a Creek | Structure & Approach Grading | 2013 | 0.192 |
| 158 | BRO 8042(29) | 5319 | Lincoln | 0.2 | | 3 S & 0.4 W of Lennox Over Long Creek | Structure & Approach Grading | 2013 | 0.282 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|---------------------------------------------------------------------------|----------------|------|------------|--------|--------------|---------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 159 | BRO 8042(39) | 00K2 | Lincoln | 0.2 | | Str on North Bridge St in Canton Over Beaver Creek (City owned) | Structure & Approach Grading | 2013 | 0.300 |
| 160 | P 0025()71 | 02QL | Miner | 10.9 | SD25 | SD25 from the Hanson/Miner County Line to the Jct. with SD34. | Mill & AC Resurfacing | 2013 | 3.186 |
| 161 | IM 0909(79)394 | 01SF | Minnehaha | 0.0 | I90E I90W | I90 - Strs 2.1 W Jct I 29 over I 90; Jct I 90 & I 29 over I 29; Jct I 90 & I 229 over I 229 | Epoxy Chip Seal | 2013 | 0.478 |
| 162 | PP 1221(02) | 02HX | Minnehaha | 0.0 | | Cleveland Ave. by Rice St. in Sioux Falls; BNSF, DOT #186696J | Upgrade railroad signal system & rehabilitate crossing | 2013 | 0.300 |
| 163 | P 1282(06) | 00KE | Minnehaha | 1.8 | | Russell Street, fm Westport Ave to Minnesota Ave in Sioux Falls | Grading, PCCP Surfacing, ROW | 2013 | 7.757 |
| 164 | P 1402(11) | 02D0 | Minnehaha | 1.0 | | West Holly Boulevard from Six Mile Road, E 1 mi. to Sandstone Ave. in Brandon | Grading, Asphalt Concrete Surfacing, Traffic Signals | 2013 | 2.900 |
| Total Project = \$2.9 mill.; STP w/Match = \$0.720; Local Funds = \$2.18) | | | | | | | | | |
| 165 | PH 2042(27) | H025 | Minnehaha | 0.0 | | Intersection of Arrowhead Parkway (Old SD42) & Sycamore in Sioux Falls | Arrowhead Parkway (Old SD42) & Sycamore - Widen for Additional Left Turn Lane on South & West Legs of Intersection | 2013 | 0.843 |
| 166 | P 6212(02) | 02DM | Minnehaha | 0.2 | | Structure 2.4E of Garretson over a creek | Structure & Approach Grading | 2013 | 0.525 |
| 167 | P 0034(145)327 | 02BH | Sanborn | 0.9 | SD34 | SD34 - Through Woonsocket | Curb Ramp Upgrades | 2013 | 0.247 |
| 168 | P 0018(160)424 | 01TL | Turner | 0.0 | US18 | US18 - 3.5 E of the JCT of SD19, Over the Vermillion River | Replace Structure (Bridge) & Approach Grading | 2013 | 1.442 |
| 169 | P 019A()25 | 02QQ | Turner | 8.1 | SD19A | SD 19A from the Jct. with SD 46 to the Jct. with SD 19 | Mill & AC Resurfacing | 2013 | 2.355 |
| 170 | P 8105(01) | 02CZ | Union | 1.9 | | Old Highway 105 from I29 Exit 4, SE 1.9 mi. to Military Road in North Sioux City | Mill & AC Resurfacing | 2013 | 0.428 |
| 171 | BRO 8064(27) | 01DZ | Union | 0.2 | | Structure 10.9S of Beresford over Brule Creek | Structure & Approach Grading | 2013 | 0.610 |
| 172 | PH 000S(236) | 01UJ | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Durable Pavement Marking | 2013 | 0.525 |
| 173 | PH 000S(221) | 02C6 | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Install Rumble Strips | 2013 | 0.300 |
| 174 | P 000S(00) | 01XN | Regionwide | 0.0 | | Various Locations in the Mitchell Region | County Pavement Marking | 2013 | 0.372 |
| State = 60%, \$0.223 Local = 40%, \$0.149 Total = \$0.372 | | | | | | | | | |
| 175 | P 000S(251) | 01XK | Statewide | 0.0 | | Statewide | Safe Routes To School | 2013 | 0.100 |
| 176 | PH 000S(239) | 01UM | Statewide | 0.0 | | Statewide | Various Miscellaneous projects identified by the Road Safety Audit Review (RSAR) | 2013 | 0.500 |
| 177 | PH 0000(46) | 01UN | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2013 | 0.065 |
| 178 | PH 0000(25) | 00LJ | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2013 | 0.065 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|-----------------------------------|--------------|-------------------|--------|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 179 | PH 0000(49) | 02AK | Statewide | 0.0 | | Public Roads Traveled Statewide | Preliminary Engineering for Conducting Road Safety Audit Reviews (RSAR) | 2013 | 0.030 |
| 180 | HS 2701(13)13 | 02CW | Statewide | 0.0 | | Statewide | Local Government Traffic Engineering Services Performed by the SDDOT Traffic & Safety Engineer. | 2013 | 0.115 |
| 181 | BR NBIS(28) | 01XZ | Statewide | 0.0 | | Statewide | Bridge Inspections, Scour Analysis | 2013 | 0.636 |
| 182 | IM 000S() | 02PD | Statewide | 0.0 | | Statewide | Guardrail Replacement | 2013 | 2.000 |
| 183 | P DBEC()13 | 02TZ | Statewide | 0.0 | | DBEC Certification Services Statewide for CY2013 | DBEC Certification Services Statewide for CY2013 | 2013 | 0.069 |
| 184 | SS FY12() | 02TY | Statewide | 0.0 | | DBE Supportive Services for CY13 | DBE Supportive Services for CY13 | 2013 | 0.162 |
| 185 | BRF 000S() | 02RN | Statewide | 0.0 | | Statewide | FY 2013 Bridge Inspection Costs | 2013 | 0.849 |
| 186 | P 000S() | 02U6 | Statewide | 0.0 | | Statewide | Wetland Mitigation | 2013 | 0.500 |
| 187 | BRO 8002(10) | 00ZR | Aurora | 0.2 | | Structure 9.5N of White Lake over a creek | Structure & Approach Grading | 2014 | 0.223 |
| 188 | BRF 0044(158)291 | 02A9 | Charles Mix | 0.0 | SD44 | SD44 - Missouri River Bridge Over Lake Francis Case | Substructure Work | 2014 | 2.165 |
| 189 | BRO 8012(16) | 01DM | Charles Mix | 0.2 | | Structure 9S & 1.3 E of Ravina over a creek | Structure & Approach Grading | 2014 | 0.255 |
| 190 | BRO 8014(26) | 6867 | Clay | 0.2 | | 5.6 S & 11 E of Irene Over a Creek | Structure & Approach Grading | 2014 | 0.233 |
| 191 | BRF 0037(109)80 BRF 0042()311 | 6496 02RS | Davison Hanson | 0.0 | SD37N SD37S SD42 | SD37 - 4.6 S of the Sanborn Co Line over Morris Creek & 2.7 Mi N of the I90 Loop Over the Lake Mitchell Spillway; SD42, 7.5 Mi E of the Davision Co Line Over the James River | Deck Overlay, Joint Modification, Approach Guardrail & Approach Pavement; Abutment Repr & Berm Berm Repr; Bearing Retrofit, Bent Cap Repair and Coverplates | 2014 | 0.764 |
| 192 | BRO 8027(29) | 00QR | Gregory | 0.2 | | 2 W & 0.1 S of SD44/SD47 Over a Creek | Structure & Approach Grading | 2014 | 0.237 |
| 193 | NH 0018(167)250 | 02BL | Gregory Tripp | 3.9 | US18 US18E US18W | US18E - Through Winner; US18 Through Winner & Gregory | Curb Ramp Upgrades | 2014 | 0.406 |
| 194 | P 0034()386 | 02R4 | Lake | 1.0 | SD34 | SD34, from US81 East to Washington Avenue in Madison | Replace City Owned System Missing 50% of Poles | 2014 | 0.186 |
| 195 | BRO 8042(09) | 6093 | Lincoln | 0.2 | | 8 S & 1.6 E of Lennox Over Snake Creek | Structure & Approach Grading | 2014 | 0.221 |
| 196 | BRO 8042(02) | 312M | Lincoln | 0.2 | | 9.5 S & 2.0 E of Lennox Over a Creek | Structure & Approach Grading | 2014 | 0.213 |
| 197 | BRO 8044(07) | 01DV | McCook | 0.2 | | Structure 2S & 0.9W of Salem over the W. Fork of the Vermillion River | Structure & Approach Grading | 2014 | 0.320 |
| 198 | IM 0909(81)406 | 021X | Minnehaha | 0.0 | I90E I90W | Over Split Rock Creek | Scour Protection | 2014 | 0.195 |
| 199 | P 0115()102 | 025C | Minnehaha | 5.5 | SD115 | SD115 - Fm south of Dell Rapids to the Jct. with I29 & Str.s - 0.5, 0.2 S & 0.1 W of Dell Rapids Over the S Fork of the Big Sioux River, the Big Sioux River, & a Creek | PCCP Resurfacing and Deck Overlay, Replace Joints, Bridge Rail Retrofit, Replace Bridge Rail, & Zone Paint, Approach Guardrail & Approach Pavement and Fatigue Retrofit | 2014 | 9.434 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|-----------------------------------------------------|----------------------|--------------------|--------|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------|
| 200 | BRF 0011(59)99 BRF 0013(15)112 BRF 0032()421 | 01SB 01SC 02RP | Minnehaha Moody | 0.0 | SD11 SD13 SD32 | SD11 - 3.4 SW Minnesota State Line over Pipestone Ck; SD13 - 4.1 S, 4.9 S & 5.2 S of the Brookings Co Line over Spring Ck; SD32, 1.7 Mi W of the SD13 Jct Over the Big Sioux River | Epoxy Chip Seal, Deck Overlay, Approach Rail, Approach Pavement, Joint Modification, Joint Replacement & Bent Cap Repair; Bridge Rail Retrofit | 2014 | 1.212 |
| 201 | BRO 8050(46) | 030S | Minnehaha | 0.2 | | 4 N & 0.3 W of Corson Over W Pipestone Creek | Structure & Approach Grading | 2014 | 0.450 |
| 202 | BRO 8050(63) | 01E2 | Minnehaha | 0.2 | | Structure on Garfield Street in Dell Rapids over the Big Sioux River (City owned) | Structure & Approach Grading | 2014 | 1.200 |
| 203 | BRO 8051(10) | H097 | Moody | 0.2 | | 6 E & 2.3 N of Colman over a Creek | Structure & Approach Grading | 2014 | 0.259 |
| 204 | BRF 6355(09) | 01W8 | Turner | 0.2 | | Structure 0.9N of Marion over the West Fork of the Vermillion River (447 St) | Structure & Approach Grading | 2014 | 0.560 |
| 205 | BRF 6397(03) | 01DY | Union | 0.2 | | Structure 4W & 2S of Alcester over E. Brule Creek | Structure & Approach Grading | 2014 | 0.345 |
| 206 | PH 000S(255) | 02B0 | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Durable Pavement Marking | 2014 | 0.550 |
| 207 | PH 000S(222) | 02C7 | Regionwide | 0.0 | | Various Locations on the State System in the Mitchell Region | Install Rumble Strips | 2014 | 0.300 |
| 208 | P 000S(00) | 02DR | Regionwide | 0.0 | | Various Locations in the Mitchell Region | County Pavement Marking | 2014 | 0.372 |
| | | | | | | State = 60%, \$0.223 Local = 40%, \$0.149 Total = \$0.372 | | | |
| 209 | LR 2014(15)0 | 022D | Statewide | 0.0 | | 2014 Resurfacing & Rehabilitation Projects Throughout South Dakota | Highway Resurfacing/Rehabilitation | 2014 | 68.325 |
| 210 | P 000S(259) | 02BR | Statewide | 0.0 | | Statewide | Safe Routes To School | 2014 | 0.100 |
| 211 | PH 0000(25) | 00LJ | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2014 | 0.065 |
| 212 | PH 000S(257) | 02AC | Statewide | 0.0 | | Statewide | Various Miscellaneous projects identified by the Road Safety Audit Review (RSAR) | 2014 | 0.500 |
| 213 | PH 000S(260) | 02AD | Statewide | 0.0 | | Public Roads Traveled Statewide | Preliminary Engineering for Conducting Road Safety Audit Reviews (RSAR) | 2014 | 0.030 |
| 214 | PH 000S(258) | 02AM | Statewide | 0.0 | | Various Township Roads Statewide | Signing & Delineation | 2014 | 0.200 |
| 215 | PH 0000(50) | 02AE | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2014 | 0.065 |
| 216 | HS 4701(13)14 | 02CU | Statewide | 0.0 | | Statewide | Local Government Traffic Engineering Services Performed by the SDDOT Traffic & Safety Engineer. | 2014 | 0.115 |
| 217 | BR NBIS(29) | 02DZ | Statewide | 0.0 | | Statewide | Bridge Inspections, Scour Analysis | 2014 | 1.135 |
| 218 | IM 000S() | 02PM | Statewide | 0.0 | | Statewide | Guardrail Replacement | 2014 | 2.000 |
| 219 | P 000S() | 02U2 | Statewide | 0.0 | | Statewide | Wetland Mitigation | 2014 | 0.500 |
| 220 | P DBEC()14 | 02U0 | Statewide | 0.0 | | DBEC Certification Services Statewide for CY2014 | DBEC Certification Services Statewide for CY2014 | 2014 | 0.070 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-------------------------------------------------------------------------------------|----------------------------------------|----------------------|------------------|--------|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-------------|--------------------|
| 221 | SS FY13() | 02U1 | Statewide | 0.0 | | DBE Supportive Services for CY14 | DBE Supportive Services for CY14 | 2014 | 0.166 |
| 222 | BRF 000S() | 02RT | Statewide | 0.0 | | Statewide | FY 2014 Bridge Inspection Costs | 2014 | 0.866 |
| 223 | BRO 8002(06) | 00Z8 | Aurora | 0.2 | | Structure 1.8E & 11N of Plankinton over a creek | Structure & Approach Grading | 2015 | 0.224 |
| 224 | BRF 0050(90)295 | 6497 | Charles Mix | 0.0 | SD50 | SD50 - 5.3 S of SD44E & 4.1 & 4.3 S of Geddes over Pease Creek | Deck Overlay, Approach Guardrail & Approach Pavement | 2015 | 0.453 |
| 225 | P 6198(04) P 6804(07) P 6199(02) | 01E9 01EA 01FK | Charles Mix | 11.0 | | Fm SD50 at Geddes W 7 mi. on 285 St to 367 Ave (FAS 6198), N 3 mi. on 367 Ave to 282 St (FAS 6804, N 1 mi. on 367 Ave to 281 St (FAS 6199) (Segment #38) | AC Overlay | 2015 | 1.759 |
| Total Project Estimate = \$1.76 mill. (STP w/Match - \$0.500, Local Funds - \$1.26) | | | | | | | | | |
| 226 | P 6370(08) | 00CU | Clay | 3.0 | | Fm 4S of Wakonda, W 3 mi. (306th St. from 452nd Ave. E 3 mi. to 455th Ave.) | Process In Place & AC Overlay | 2015 | 0.540 |
| 227 | BRO 8014(25) | 6868 | Clay | 0.2 | | 0.6 S & 15 E of Irene Over Ash Creek | Structure & Approach Grading | 2015 | 0.282 |
| 228 | IM 0907(53)319 | 6666 | Davison Hanson | 14.5 | I90W | I90 - WBL, Fm Mount Vernon to the James River & Str Over the James River | Remove & Replace PCCP & 2 Cross Overs and Joint Replacement On The James River Structure | 2015 | 15.972 |
| 229 | P 6479(03) | H093 | Gregory | 4.0 | | Fm 6N of Dallas at 281 St, N 4 mi. on 333 Ave to SD44 (Co Rd #3) | Grading & Gravel Surfacing | 2015 | 0.880 |
| 230 | BRO 8034(25) | 01WG | Hutchinson | 0.2 | | Structure 6E & 1.4N of Parkston over Pony Creek (27360 417 Ave) | Structure & Approach Grading | 2015 | 0.229 |
| 231 | BRO 8034() | 02T2 | Hutchinson | 0.2 | | Structure 4N & 7.9W of Freeman over Wolf Creek on 274 St. SN 34-261-060 | Structure & Approach Grading | 2015 | 0.450 |
| 232 | P 0019(36)73 | 026D | Lake Minnehaha | 23.5 | SD19 | SD19 - Fm the Jct. of SD38 to the Jct of SD34 | AC Resurfacing; AC Surfacing | 2015 | 7.265 |
| 233 | P 6307(08) | H126 | Lake | 0.5 | | Egan Ave fm 2nd St N to 9th St N in Madison | Grading, Curb & Gutter & PCC Paving | 2015 | 0.750 |
| 234 | PH 8040() | 02MW | Lake | 0.0 | | Various County, City, & Township Roads in Lake County | Signing & Delineation | 2015 | 0.600 |
| 235 | P 0115()76 | 0214 | Lincoln | 3.0 | SD115 | SD115 - Fm the Lincoln County 110 (Harrisburg corner) to 85th St. in Sioux Falls. | Reconstruct to 4 lane segment, Traffic Signals | 2015 | 7.728 |
| 236 | P 0017()42 | 028V | Lincoln | 0.8 | SD17 | SD17 - Fm the Jct. with SD44 to the north city limits in Lennox | Corridor Preservation, Grading & AC Surfacing | 2015 | 3.616 |
| 237 | BRO 8042(33) | 6581 | Lincoln | 0.2 | | 7 S & 3.9 W of Canton Over a Creek | Structure & Approach Grading | 2015 | 0.250 |
| 238 | BRO 8042(34) | H061 | Lincoln | 0.2 | | 4 W & 6.9 S of Canton Over Saddle Creek | Structure & Approach Grading | 2015 | 0.250 |
| 239 | BRO 8044(08) | 02E2 | McCook | 0.2 | | Structure 8.5S & 1.1E of Montrose over the East Fork of the Vermillion River | Structure & Approach Grading | 2015 | 0.250 |
| 240 | PH 8044() | 02MY | McCook Minnehaha | 0.0 | | Various County, City, & Township Roads in McCook County and various township roads in Minnehaha County | Signing & Delineation | 2015 | 0.600 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|------------------------------|--------------|------------|--------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------|--------------------|
| 241 | BRF 0081()54 | 02S4 | McCook | 0.0 | US81 | US81, Str. 3.2 S I 90 Interchange over West Fork Vermillion Rv | Deck Overlay, Approach Slabs, Approach Guardrail | 2015 | 0.237 |
| 242 | BRO 8049(18) | 02E0 | Miner | 0.2 | | Structure on Main Street in Carthage over Redstone Creek (City owned) | Structure & Approach Grading | 2015 | 0.265 |
| 243 | PH 1400(10) | 00YE | Minnehaha | 0.0 | | City of Sioux Falls - Western & 41st St. | Install Right Turn Lane EB to SB and WB to NB, Widen S Leg For Additional Lt Turn Lane | 2015 | 0.643 |
| 244 | BRO 8050(62) | 01E1 | Minnehaha | 0.2 | | Structure on Third St. in Dell Rapids over a creek (City owned) | Structure & Approach Grading | 2015 | 0.250 |
| 245 | IM 2292()4 | 02PN | Minnehaha | 0.0 | I229S | Over Cliff Ave | Bent Cap Repair | 2015 | 0.138 |
| 246 | BRF 0011()88 | 02S1 | Minnehaha | 0.0 | SD11 | 7.2 N I 90 Interchange over West Pipestone Ck | Scour Protection | 2015 | 0.082 |
| 247 | BRO 8056(12) | 02E3 | Sanborn | 0.2 | | Structure 0.5E & 3.4N of Artesian over a creek | Structure & Approach Grading | 2015 | 0.272 |
| 248 | BRF 0037()111 | 02S5 | Sanborn | 0.0 | SD37S | SD37, SBL Str. 3.3 S Jct SD 224 over Sand Ck | Deck Overlay, Approach Slabs and Approach Guardrail | 2015 | 0.279 |
| 249 | BRF 6102(06) | 01WK | Turner | 0.2 | | Structure 2.9E of Viborg over a creek (291 St) | Structure & Approach Grading | 2015 | 0.599 |
| 250 | P 0046(48)365 | 028K | Union | 1.0 | SD46 | SD46 - Fm 13th St. SW to Ash St. in Beresford | Remove & Replace PCCP and Roadway Lighting | 2015 | 4.720 |
| 251 | IM 0291()35 P 0048()375 | 02PR 02PS | Union | 0.0 | I29N SD48 | I29 - 4.5 Mi N of SD48 Over a Creek; SD48, 3.8 Mi E of I29 Over a Creek | Scour Protection | 2015 | 0.155 |
| 252 | IM 0291()2 | 02PT | Union | 0.0 | I29N I29S | N Sioux City Interchange Over River Street | Deck Overlay, Approach Slabs and Approach Guardrail | 2015 | 0.507 |
| 253 | NH 0050()383 | 6926 | Yankton | 1.5 | SD50 | SD50 - East 4th Street, fm the S Jct of US81 E to Ferdig Ave in Yankton ; SD50, Str.s 1.3 W Jct US 81 over Marne Creek & 0.8 E Jct US 81 over Marne Creek | Reconstruct; Deck Overlay, Approach Slabs, Approach Guardrail | 2015 | 8.451 |
| 254 | PH 0020() | 02MQ | Regionwide | 0.0 | | Various locations on the State System in the Mitchell Region | Durable Pavement Marking | 2015 | 0.550 |
| 255 | PH 0020() | 02N1 | Regionwide | 0.0 | | Various locations on the State System in the Mitchell Region | Install Rumble Strips | 2015 | 0.300 |
| 256 | P 000S(00) | 02SR | Regionwide | 0.0 | | Various Locations in the Mitchell Region | County Pavement Marking | 2015 | 0.372 |
| | | | | | | \$0.372 - State funds at 60/40 (State - \$0.223, County - \$0.149) | | | |
| 257 | PH 000S() | 02N4 | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Conducting Road Safety Audit Reviews (RSAR) | 2015 | 0.030 |
| 258 | HS 2701()15 | 02N5 | Statewide | 0.0 | | Statewide | Local Government traffic engineering services performed by the SDDOT Traffic & Safety Engineer | 2015 | 0.115 |
| 259 | PH 000S() | 02N6 | Statewide | 0.0 | | Public Traveled Roads Statewide | Preliminary Engineering for Roadway Safety Improvement | 2015 | 0.065 |
| 260 | IM 000S() | 02PQ | Statewide | 0.0 | | Statewide | Guardrail Replacement | 2015 | 2.000 |
| 261 | LR 2015()0 | 02Q8 | Statewide | 0.0 | | 2015 Resurfacing & Rehabilitation Projects Throughout South Dakota | Highway Resurfacing/Rehabilitation | 2015 | 76.873 |
| 262 | P 000S() | 02U3 | Statewide | 0.0 | | Statewide | Wetland Mitigation | 2015 | 0.500 |

| # | Project Number | PCN | County | Length | Route | Location of Project | Type of Improvement | Fiscal Year | Total Cost(Mil \$) |
|-----|----------------|------|-----------|--------|-------|--------------------------------------------------|--------------------------------------------------|-------------|--------------------|
| 263 | P DBEC()15 | 02U5 | Statewide | 0.0 | | DBEC Certification Services Statewide for CY2015 | DBEC Certification Services Statewide for CY2015 | 2015 | 0.072 |
| 264 | SS FY14() | 02U4 | Statewide | 0.0 | | DBE Supportive Services for CY15 | DBE Supportive Services for CY15 | 2015 | 0.169 |
| 265 | BRF 000S() | 02RU | Statewide | 0.0 | | Statewide | FY 2015 Bridge Inspection Costs | 2015 | 0.883 |
| 266 | P 000S() | 02SG | Statewide | 0.0 | | Statewide | Safe Routes To School | 2015 | 0.100 |
| 267 | BR NBIS() | 02T3 | Statewide | 0.0 | | Statewide | Bridge Inspections, Scour Analysis | 2015 | 0.636 |